I Inspec Homes

Professional Home Inspector Joe Acevedo TREC #20294 www.IInspecHomes.com IInpsecHomes@gmail.com

Please Call, Text or Email with any Questions



INVOICE I Inspec Homes 2003 Fall Creek Dr Leander, TX 78641

Phone 512=587-1988 IInspecHomes@gmail.com

TREC 20294

SOLD TO:	INVOICE NUMBER	20131204-01
	INVOICE DATE	12/04/2013
TX	LOCATION	<none></none>
	DATE	
	REALTOR	

DESCRIPTION	PRICE	AMOUNT
	SUBTOTAL	\$0.00
		\$0.00
	TAX	\$0.00
	TOTAL	\$0.00
	BALANCE DUE	\$0.00

THANK YOU FOR YOUR BUSINESS!

Phone: 512=587-1988

Fax:

Email: IInspecHomes @gmail.com

PROPERTY INSPECTION REPORT

_	(Name of Client)	
Concerning:	, TX	
o o	(Address of Inspected Property)
By:	Joe Acevedo, Lic #20294	12/04/2013
•	(Name and License Number of Inspector)	(Date)
	(Name, License Number and Signature of Sponsoring Inspector,	if required)

This property inspection report may include an inspection agreement (contract), addenda, and other information related to property conditions. If any item or comment is unclear, you should ask the inspector to clarify the findings. It is important that you carefully read ALL of this information.

This inspection is subject to the rules ("Rules") of the Texas Real Estate Commission ("TREC"), which can be found at www.trec.state.tx.us.

The TREC Standards of Practice (Sections 535.227-535.233 of the Rules) are the minimum standards for inspections by TREC-licensed inspectors. An inspection addresses only those components and conditions that are present, visible, and accessible at the time of the inspection. While there may be other parts, components or systems present, only those items specifically noted as being inspected were inspected. The inspector is not required to move furnishings or stored items. The inspection report may address issues that are code-based or may refer to a particular code; however, this is NOT a code compliance inspection and does NOT verify compliance with manufacturer's installation instructions. The inspection does NOT imply insurability or warrantability of the structure or its components. Although some safety issues may be addressed in this report, this inspection is NOT a safety/code inspection, and the inspector is NOT required to identify all potential hazards.

In this report, the inspector will note which systems and components were Inspected (I), Not Inspected (NI), Not Present (NP), and/or Deficient (D). General deficiencies include inoperability, material distress, water penetration, damage, deterioration, missing parts, and unsuitable installation. Comments may be provided by the inspector whether or not an item is deemed deficient. The inspector is not required to prioritize or emphasize the importance of one deficiency over another.

Some items reported as Deficient may be considered life-safety upgrades to the property. For more information, refer to Texas Real Estate Consumer Notice Concerning Recognized Hazards, form OP-I.

This property inspection is not an exhaustive inspection of the structure, systems, or components. The inspection may not reveal all deficiencies. A real estate inspection helps to reduce some of the risk involved in purchasing a home, but it cannot eliminate these risks, nor can the inspection anticipate future events or changes in performance due to changes in use or occupancy. It is recommended that you obtain as much information as is available about this property, including any seller's disclosures, previous inspection reports, engineering reports, building/remodeling permits, and reports performed for or by relocation companies, municipal inspection departments, lenders, insurers, and appraisers. You should also attempt to determine whether repairs, renovation, remodeling, additions, or other such activities have taken place at this property. It is not the inspector's responsibility to confirm that information obtained from these sources is complete or accurate or that this inspection is consistent with the opinions expressed in previous or future reports.

ITEMS IDENTIFIED IN THE REPORT DO NOT OBLIGATE ANY PARTY TO MAKE REPAIRS OR TAKE OTHER ACTIONS, NOR IS THE PURCHASER REQUIRED TO REQUEST THAT THE SELLER TAKE ANY ACTION. When a deficiency is reported, it is the client's responsibility to obtain

Report Identification: 20131	1204-01, , , TX	
------------------------------	-----------------	--

further evaluations and/or cost estimates from qualified service professionals. Any such follow-up should take place prior to the expiration of any time limitations such as option periods. Evaluations by qualified tradesmen may lead to the discovery of additional deficiencies which may involve additional repair costs. Failure to address deficiencies or comments noted in this report may lead to further damage of the structure or systems and add to the original repair costs. The inspector is not required to provide follow-up services to verify that proper repairs have been made.

Property conditions change with time and use. For example, mechanical devices can fail at any time, plumbing gaskets and seals may crack if the appliance or plumbing fixture is not used often, roof leaks can occur at any time regardless of the apparent condition of the roof, and the performance of the structure and the systems may change due to changes in use or occupancy, effects of weather, etc. These changes or repairs made to the structure after the inspection may render information contained herein obsolete or invalid. This report is provided for the specific benefit of the client named above and is based on observations at the time of the inspection. If you did not hire the inspector yourself, reliance on this report may provide incomplete or outdated information. Repairs, professional opinions or additional inspection reports may affect the meaning of the information in this report. It is recommended that you hire a licensed inspector to perform an inspection to meet your specific needs and to provide you with current information concerning this property.

ADDITIONAL INFORMATION PROVIDED BY INSPECTOR							
Present at Inspection:	☑ Buyer	☐ Selling Agent	☐ Listing Agent	☐ Occupant			
Building Status:	□ Vacant	☑ Owner Occupied	☐ Tenant Occupied	☐ Other			
Weather Conditions:	☐ Fair	☑ Cloudy	☐ Rain	Temp:			
Utilities On:	✓ Yes	☐ No Water	☐ No Electricity	☐ No Gas			
Special Notes:							
	INIACCE	COLDI E OD ODOTDIJ	CTED ADEAS				
Поле	INACCE	SSIBLE OR OBSTRU					
☐ Sub Flooring			e is Limited - Viewed from				
☐ Floors Covered		☐ Plumbing A	Areas - Only Visible Plum	bing Inspected			
☐ Walls/Ceilings Covered or Freshly Painted ☐ Siding Over Older Existing Siding							
☐ Behind/Under Furniture and/or Stored Items ☐ Crawl Space is limited - Viewed From Accessible Areas							
			rt; it is beyond the scope				
the present time. Any obtained.	y reference of	water intrusion is recom	mended that a profession	nal investigation be			
NOTICE: THIS REPORT IS PAID FOR BY AND PREPARED FOR THE CLIENT NAMED ABOVE.							
THIS REPORT IS N	THIS REPORT IS NOT VALID WITHOUT THE SIGNED SERVICE AGREEMENT AND IS NOT						
		TRANSFERABLE.	ı .				

REI 7-2 (8/09) Page 2 of 16

I=Inspected NI=Not Inspected NP=Not Present D=Deficient

I NI NP D

I. STRUCTURAL SYSTEMS

A. Foundations

Type of Foundation(s): Slab

Comments: At the time of inspection structural movement was found would recommend to repair/fill and monitor cracks not allowing to reappear to increase in size or in numbers.

If in the any of the acts mentioned above appear I would recommend to have the foundation further inspected/ evaluated by a Foundation Specialist.

Any trees/heavy foliage closer then 6' to the structure can cause structural damage to the foundation. Would recommend to consult with lawn service company to stop roots from growing under foundation causing further damage.

Signs of Structural Movement or Settling

☑ Cracks in brick, stone, or stucco

☑ Cracks in Parge Coat

☑ Cracks in wall(s) and / or ceiling


Performance Opinion: (An opinion on performance is mandatory)

Note: Weather conditions, drainage, leakage and other adverse factors are able to effect structures, and differential movements are likely to occur. The inspectors opinion is based on visual observations of accessible and unobstructed areas of the structure at the time of the inspection. Future performance of the structure cannot be predicted or warranted.

☑ Structural movement and/or settling noted; however, the foundation is supporting the structure at this time.

suggested Foundation Maintenance & Care - Proper drainage and moisture maintenance to all types of foundations due to the expansive nature of the area load bearing soils. Drainage must be directed away from all sides of the foundation with grade slopes. In most cases, floor coverings and/or stored articles prevent recognition of signs of settlement - cracking in all but the most severe cases. It is important to note, this was not a structural engineering survey nor was any specialized testing done of any sub-slab plumbing systems during this limited visual inspection, as these are specialized processes requiring excavation. In the event that structural movement is noted, client is advised to consult with a Structural Engineer who can isolate and identify causes, and determine what corrective steps, if any, should be considered to either correct and/or stop structural movement.





REI 7-2 (8/09) Page 3 of 16

I=Inspected NI=Not Inspected NP=Not Present D=Deficient

I NI NP D

☑ ☐ ☑ B. Grading and Drainage - Comments:

The grading slopes too much away from foundation around the house and condenser along with posts on patio decks. Would recommend to have a lawn specialist to inspect and evaluate to decrease the slope around the house and the decks.

Note: Any area where the ground or grade does not slope away from the structure is to be considered an area of improper drainage. Six inches per 10 feet.

- ☑ Trees/heavy foliage too close to the structure
- ✓ Planter(s) adjoining the structure
- Soil / lot conditions suggest further evaluation by appropriate professional, i.e., watering program, drains, etc.





\square \square \square \square \square \square \square C. Roof Covering Materials

Type(s) of Roof Covering: Asphalt Shingles

Viewed From: Edge of Roof

Comments:At the time of inspection I was not able to walk on top of the roof due to steep slope of the roof. Not walking on the roof doe's not allow me to see if there's hail damage or any other problems not visible from the roof edge.

At the time of inspection there was no signs of water leaks/ damage from inside of the attic determining damage to the roof covering.

I would recommend to have all flashing caulked around all opening on the roof to help prevent damage.

At the time of inspection there was no signs of leaks/damage around the sky lights. There known to leak due to such a big opening on the roof would recommend to caulk and monitor as much as possible.

- ✓ Flashing is lifting, ill configured, or missing
- ✓ Leaves / debris in the gutters and downspouts
- ✓ Tree branches are too close to the roof structure

REI 7-2 (8/09) Page 4 of 16

I=Inspected NI=Not Inspected NP=Not Present D=Deficient

I NI NP D



D.	Roof Structure and Attic Viewed From: Entered the Attic Approximate Average Depth of Insulation:12" Approximate Average Thickness of Vertical Insulation:12" Comments: At the time of inspection the roof structure was performing as it should nothing was cut or missing. At the time of inspection there was no voids of the insulation but can always be improved to help with efficiency.
Е.	Walls (Interior and Exterior) - Comments: Interior Walls:
	☑ Water stains on walls and/or ceilings in the dining room from a/c unit in the attic. At the time of

inspection there was no active leaks found.

Exterior Walls:

Siding Materials:	☑ Brick	☐ Stone	✓ Wood	☐ Wood byproducts	□ Stucco
	☐ Vinyl	☐ Aluminum	☐ Asbestos	☐ Cement Board	☐ Other
At the time of insp	ection the	wall over the g	garage has a g	good size crack due to	undersized linte

At the time of inspection the wall over the garage has a good size crack due to undersized lintel. Would recommend to repair/ fill cracks not allowing to reappear to increase in size or in numbers. If any of the acts mentioned above appear I would recommend to have the wall further inspected and evaluated by a licensed contractor.

At the time of inspection the wall on the side with the large tree has a good size crack due to tree too close to the structure causing damage to the foundation and the wall over that section. I would recommend to have a lawn specialist inspect and evaluate the area to prevent further damage. Some caulking around the windows and doors are needed to prevent water penetration.

There was a sign that the wood siding was put over old siding that I would recommend to keep up with paint and caulk on the wood siding to prevent future damage. There was a bolg near master bath window from moisture penetration would recommend to repair and monitor not allowing to reappear.

REI 7-2 (8/09) Page 5 of 16

I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

NI NP D

- ☑ Mortar is separated or missing in some areas
- ☑ Caulking / sealant is separated or missing in some areas
- ☑ Some cracks at the brick, stone, or stucco siding
- ☑ Wood siding is water damaged in some areas









☑ ☐ ☐ F. Ceilings and Floors - Comments:

At the time of inspection there was no signs of water stains/damage.

☑ ☐ ☑ G. Doors (**Interior** and **Exterior**) - *Comments*:

Interior Doors

At the time of inspection the interior doors were operating correctly

Exterior Doors

At the time of inspection the 3 French doors had wood rot due to water penetration from lack of caulk and paint would recommend to repair to help prevent further damage.

At the time of inspection the front door had a broken glass that should be repaired to prevent further damage.

REI 7-2 (8/09) Page 6 of 16


I=Inspected

NI=Not Inspected

NP=Not Present

D=Deficient

NI NP D



Garage Doors

Type: ☐ Metal ☐ Wood ☑ Fiberglass ☐ Doors / panels are damaged At the time of inspection there was a broken glass pane that needs to be repaired



REI 7-2 (8/09) Page 7 of 16


I=Inspected NI=Not Inspected NP=Not Present **D=Deficient** NI NP D H. Windows - Comments: Some of the windows at the time of inspection were not accessible but no broken panes or moisture penetration was found. Would recommend to caulk and paint around all windows and sky lights to prevent water penetration. ☑ Some windows are difficult to open or close due to age of the windows. ☑ Inspection of the windows was limited **Stairways (Interior and Exterior)** - Comments: **INTERIOR EXTERIOR**



☑ ☐ ☑ J. Fireplace/Chimney - *Comments:*

Type of Fireplace: \square Factory \square Masonry \square Free Standing At the time of inspection there was a crack above the hearth and behind the firebox that needs to be repaired. Due to the age of the house would recommend to have a fireplace specialist inspect and clean the fireplace to help prevent a hazard.

At the time of inspection the stairs on the patio had signs of wood rot that should be





REI 7-2 (8/09) Page 8 of 16

I=Inspected NI=Not Inspected NP=Not Present D=Deficient

I NI NP D

☑ □ □ ☑ K. Porches, Balconies, Decks, and Carports - Comments:

At the time of inspection the 1st deck that's connected to the back of the house should have the posts connected to the footings and the deck its self would recommend to have a licensed contractor to repair. The deck its self is sagging in certain areas due to wood rot that needs to be repaired by licensed contractor to prevent further damage or a hazard.

The 2nd deck on the left side of the house behind breakfast area requires rail if the deck is over 30" from the ground to prevent a hazard. There was signs of wood rot that needs to be repaired or replaced by a licensed contractor.

The 3rd deck furthest away from the house requires no openings around the railings to not exceeding 4" which had an opening of 5" that should be repaired to prevent a hazard. There was not enough support with the floor joists which I would recommend to improve or repair to prevent a hazard. The footings for the deck is not supported very well would recommend to have a licensed contractor evaluate to prevent from footing from sliding out from the deck.



REI 7-2 (8/09) Page 9 of 16

I=Inspected NI=Not Inspected NP=Not Present D=Deficient

I NI NP D

L. Other - Comments:


II. ELECTRICAL SYSTEMS


A. Service Entrance and Panels - Comments:

□ Overhead Service ☑ Underground Service

Main Disconnect Panel

At the time of inspection the electrical system was up to code when the house was built but I have to inspect the system as it was put in today. The entire house should be protected by ark fault breakers and ground fault outlets I would recommend to have a licensed electrician repair or replace system. There is oxidization on serveral breakers that should be evaluated by electrician. At the time of inspection the electrical system was working as it should.





oxdot B. Branch Circuits, Connected Devices, and Fixtures





I=Inspected NI=Not Inspected NP=Not Present D=Deficient

I NI NP D

Outlet and Switches								
☑ Improper us	se of extens	sion cords a	as permanent wi	ring around the	patio			
			house needs re					
damaged outle				,				
Ground/AR	C Fault C	Circuit Int	terrupt Safet	y Protection				
Kitchen:	☐ Yes	☑ No	☐ Partial	Bathrooms:	✓ Yes	□ No	☐ Partial	
Exterior:	✓ Yes	□ No	☐ Partial	Garage:	✓ Yes	□ No	☐ Partial	
Basement:	☐ Yes	☑ No	☐ Partial	Wet Bar:	☐ Yes	☑ No	☐ Partial	
Living:	☐ Yes	☑ No	☐ Partial	Dining:	☐ Yes	☑ No	☐ Partial	
Crawlspace:	☐ Yes	☑ No	☐ Partial	Laundry:	☐ Yes	☑ No	☐ Partial	
A/C Unit:	☐ Yes	☑ No	☐ Partial	Pool/Spa:	☐ Yes	☑ No	☐ Partial	
Bedroom: ☐ Yes ☑ No ☐ Partial								
✓ No GFCI/ARC Fault protection at one or more location. This is considered a recognized safety hazard.								

Fixtures

At the time of inspection the fixtures were working properly

Smoke and Fire Alarms

At the time of inspection the alarm was working properly

Other Electrical System Components

III. HEATING, VENTILATION AND AIR CONDITIONING SYSTEMS

☑ □ □ □ A. Heating Equipment

Type of System: Central Energy Source: Heat Pump

Comments:At the time of inspection the heat pump was working as it should would always recommend to replace or clean filters every month and clean out condensation line every couple months





REI 7-2 (8/09) Page 11 of 16

I NI NP D B. Cooling Equipment Type of System: Central - Air Conditioner Comments:At the time of inspection the differential was a little below what it should be which is sign of a coolant pressure problem would recommend to have licensed professional inspect service. The air handler plenum has a minor leak of air escaping from the system that should repaired to help with efficiency of the system. □ Unit #1: Supply Air Temp:62_°F Return Air Temp: 74_°F Temp. Differential:12°F □ Temperature differential is not within range of 14-23 degrees Fahrenheit □ Condenser unit coil fins damaged / dirty □ Air handler plenum is not properly sealed □ Lack of GFCI near unit for technician □ Unit #1: Type of Ducting: □ Flex Ducting □ Duct Board □ Metal At the time of inspection there was no signs of leaks around the ducting or vents in the attic. ducting is required to be off of the insulation to help improve the efficiency of the house. □ Inadequate support of duct work IV.PLUMBING SYSTEM A. Water Supply System and Fixtures □ Functional Flow Inadequate	Report I	Report Identification: 20131204-01, , , TX						
B. Cooling Equipment Type of System: Central - Air Conditioner Comments: At the time of inspection the differential was a little below what it should be which it sign of a coolant pressure problem would recommend to have licensed professional inspect is service. The air handler plenum has a minor leak of air escaping from the system that should repaired to help with efficiency of the system. Unit #1: Supply Air Temp:62 _ °F Return Air Temp: 74_ °F Temp. Differential:12 _ °F Temperature differential is not within range of 14-23 degrees Fahrenheit Condenser unit coil fins damaged / dirty Air handler plenum is not properly sealed Lack of GFCI near unit for technician C. Duct System, Chases, and Vents - Comments: Type of Ducting: Flex Ducting Duct Board Metal At the time of inspection there was no signs of leaks around the ducting or vents in the attic. ducting is required to be off of the insulation to help improve the efficiency of the house. Inadequate support of duct work IV.PLUMBING SYSTEM A. Water Supply System and Fixtures	I=Insp	ected	Į	NI=Not Inspected	NP=Not Present	D=Deficient		
Type of System: Central - Air Conditioner Comments:At the time of inspection the differential was a little below what it should be which it sign of a coolant pressure problem would recommend to have licensed professional inspect service. The air handler plenum has a minor leak of air escaping from the system that should repaired to help with efficiency of the system. □ Unit #1: Supply Air Temp:62 _ °F Return Air Temp: 74 _ °F Temp. Differential:12 °F □ Temperature differential is not within range of 14-23 degrees Fahrenheit □ Condenser unit coil fins damaged / dirty □ Air handler plenum is not properly sealed □ Lack of GFCI near unit for technician □ Duct Board □ Metal At the time of inspection there was no signs of leaks around the ducting or vents in the attic. ducting is required to be off of the insulation to help improve the efficiency of the house. □ Inadequate support of duct work IV.PLUMBING SYSTEM A. Water Supply System and Fixtures	I NI	NP	D					
Air handler plenum is not properly sealed Lack of GFCI near unit for technician C. Duct System, Chases, and Vents - Comments: Type of Ducting:	☑ □		V	Type of System: Central Comments: At the time of sign of a coolant press service. The air handle repaired to help with each of the supply Air Temp:6	of inspection the differentia ure problem would recoming or plenum has a minor leak fficiency of the system. 2°F Return Air Temp	mend to have licensed professional inspe t of air escaping from the system that sho o: <u>74</u> °F Temp. Differential:12 °F	ect and ould be	
Type of Ducting: ☑ Flex Ducting ☐ Duct Board ☐ Metal At the time of inspection there was no signs of leaks around the ducting or vents in the attic. ducting is required to be off of the insulation to help improve the efficiency of the house. ☑ Inadequate support of duct work IV.PLUMBING SYSTEM A. Water Supply System and Fixtures				☑ Air handler plenum	is not properly sealed			
✓ □ □ ✓ A. Water Supply System and Fixtures			\square	Type of Ducting: At the time of inspection ducting is required to be	☑ Flex Ducting ☐ Due on there was no signs of lesse off of the insulation to he	aks around the ducting or vents in the att	ic. The	
✓ □ □ ✓ A. Water Supply System and Fixtures								
				IV.PLUMBING SYST	EM			
· Functional Flow Inadequate			$\overline{\checkmark}$	A. Water Supply System a	and Fixtures	_		
Location of main water supply valve: front right Static water pressure reading: 70				Static water pressure red Comments: At the time of prevent damage to the Water Source: ☑ Pu	ding: 70 □ below □ Lack of inspection the water president plumbing and giving efficiblic □ Private Sewer	of reducing valve over 80 psi essure was between 40-80 which it should ent pressure Type: ☑ Public ☐ Private	·	

REI 7-2 (8/09) Page 12 of 16

Report Identification	on: 20131204-01, , , TX			
I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient	
I NI NP D				
	water damage but water penetration in help prevent a brok Commodes	ime of inspection the sin both bathrooms the nto the walls. All fauce ten pipe due to the age	shower showed no signs of leaks ogrout should be caulked to prevenets needs to be caulked and tightenet of the house. The was no signs of leaks or non	nt
	Exterior Plumbing Comments: At the t	ime of inspection ther	e was no signs of corrosion or leak e was no signs of leaks but would vent damage.	<u>:</u>
	☑ Exterior hose bibs of	lo not have back-flow prev	ention	
	B. Drains, Wastes, and Ve	nts - Comments: tion there was no signs	of clogs or leaks.	
	C. Water Heating Equipm Energy Source: Electric	•		
			er was working properly but did not have very plumber to increase work area around the	
	☑ Electrical disconnec	ct missing/inadequate clear	ance	
	Water heater Temp	erature and Pressure F	Relief Valve	
	D. Hydro-Massage Therap	by Equipment - Comments:		
	V. APPLIANCES			
	A. Dishwasher - Comments At the time of inspec excessive vibrations		working properly no signs of leaks or	
	B. Food Waste Disposer -	Comments:		

At the time of inspection the disposer was working properly had no signs of leaks or excessive vibrations. Romex wire is not allowed to service disposer it should be

repaired/replaced by licensed electrician for safety hazard

REI 7-2 (8/09) Page 13 of 16

I=Inspected NI=Not Inspected NP=Not Present D=Deficient

NI NP D



	$\overline{\mathbf{V}}$	$\overline{\mathbf{A}}$	C.	Range Exhaust Vent - Comments:
V			D.	Ranges, Cooktops, and Ovens - Comments: Range Type: ☑ Electric □ Gas At the time of inspection the range was not damage and working properly
				Oven(s): Unit #1: ☑ Electric ☐ Gas At the time of inspection the oven was not damage and working properly
V			Е.	Microwave Oven - Comments: At the time of inspection the microwave was not damage and working properly
V			F.	Trash Compactor - Comments: At the time of the inspection the compactor was working but had an excessive vibration going on that should be repaired.



I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient	
I NI NP D				
	G. Mechanical Exhaust Ve		 Comments: vere working properly and vented 	d correctly.
	needs to be adjusted		was working properly but the aut	o reverse
	I. Doorbell and Chimes - At the time of inspec		vorking properly and not damage	١.
	J. Dryer Vents - Comment At the time of inspec safety		s a little dirty and should be clean	ed out for
	VI.OPTIONAL SYSTI	EMS		
		s r freeze sensor	phon devices and back flow prevent one heads	er
	B. Swimming Pools, Spas,	Hot Tubs, and Equipment		
	C. Outbuildings - Commen	ats:		
	D. Outdoor Cooking Equip	pment		
	E. Gas Supply Systems - C	Comments:		
	F. Private Water Wells (A	coliform analysis is recomn	nended.)	

REI 7-2 (8/09) Page 15 of 16

Report Identification: 20131204-01, , , TX				
I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient	
I NI NP D				
	G. Private Sewage Disposal (Septic) Systems			
	H. Whole-House Vacuum Systems - Comments:			
	I. Other Built-in Applian	nces - Comments:		

I. Other Built-in Appliances - Comments:

Page 16 of 16



TEXAS REAL ESTATE CONSUMER NOTICE CONCERNING HAZARDS OR DEFICIENCIES

Each year, Texans sustain property damage and are injured by accidents in the home. While some accidents may not be avoidable, many other accidents, injuries, and deaths may be avoided through the identification and repair of certain hazardous conditions. Examples of such hazards include:

- improperly installed or missing ground fault circuit protection (GFCI) devices for electrical receptacles in garages, bathrooms, kitchens, and exterior areas;
- improperly installed or missing arc fault protection (AFCI) devices for electrical receptacles in family rooms, dining rooms, living rooms, parlors, libraries, dens, bedrooms, sunrooms, recreations rooms, closets, hallways, or similar rooms or areas;
- ordinary glass in locations where modern construction techniques call for safety glass;
- the lack of fire safety features such as smoke alarms, fire-rated doors in certain locations, and functional emergency escape and rescue openings in bedrooms;
- excessive spacing between balusters on stairways and porches;
- improperly installed appliances;
- improperly installed or defective safety devices; and
- lack of electrical bonding and grounding.

To ensure that consumers are informed of hazards such as these, the Texas Real Estate Commission (TREC) has adopted Standards of Practice requiring licensed inspectors to report these conditions as "Deficient" when performing an inspection for a buyer or seller, if they can be reasonably determined.

These conditions may not have violated building codes or common practices at the time of the construction of the home, or they may have been "grandfathered" because they were present prior to the adoption of codes prohibiting such conditions. While the TREC Standards of Practice do not require inspectors to perform a code compliance inspection, TREC considers the potential for injury or property loss from the hazards addressed in the Standards of Practice to be significant enough to warrant this notice.

Contract forms developed by TREC for use by its real estate licensees also inform the buyer of the right to have the home inspected and can provide an option clause permitting the buyer to terminate the contract within a specified time. Neither the Standards of Practice nor the TREC contract forms requires a seller to remedy conditions revealed by an inspection. The decision to correct a hazard or any deficiency identified in an inspection report is left to the parties to the contract for the sale or purchase of the home.

This form has been approved by the Texas Real Estate Commission for voluntary use by its licensees. Copies of TREC rules governing real estate brokers, salesperson and real estate inspectors are available at nominal cost from TREC. Texas Real Estate Commission, P.O. Box 12188, Austin, TX 78711-2188, 1-800-250-8732 or (512) 459-6544 (http://www.trec.state.tx.us)